

ABSTRACT OF THE DISCLOSURE

To form a center tap (CT), at least two coils must be formed. This increases the number of steps in the winding process and decreases the workability. To 5 prevent this, a conductor having a plurality of plate portions that are connected to each other at one vertex of a rectangular shape is formed. The conductor is wound on a winding shaft, thus forming two coils.